

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 3 prime mover on pumping unit



Photo 4 pumping unit

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 5 stained soil at well head



Photo 6 stained & unused risers

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 7 stained soil out side equipment berm



Photo 8 production equipment

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 9 produce water tank



Photo 10 crude tanks



Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 11 tank battery



Photo 12 overgrown vegetation

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 13 vehicle tracking & overgrown vegetation



Photo 14 vehicle tracking

Inspection Photos
Location Name: Nork York 1
Location ID: 319889



Photo 15 vehicle tracking