

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 9/19/2023



Wellheads – Photo #06468



Separators – Photo #06472



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 9/19/2023



**Tank Battery – Photo #06473**



**Location Lacks Stabilization – Photo #06470**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 9/19/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #06471