

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 9/19/2023



Entrance to Location – Photo #06475



Wellhead – Photo #06476

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 9/19/2023



Separator – Photo #06477



Tank Battery – Photo #06478

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 9/19/2023



**Rill Erosion Cutting Through Access Road – Photo #06481**