

Final Reclamation Inspection

September 1st, 2023

Operator: BP American Production Co - 10000

Location ID: 413525

Inspection Document #: 714000008

La Plata County, CO

Township: NWSW 21 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 1. Overview of the disturbance taken from the southern edge.
Area is dominated by western wheatgrass and smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09747

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 2. View flowering musk thistle located in the southwest corner of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09747

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 3. View of the southern edge of the disturbance. Several wooden stakes remain and wattle stormwater BMPs that need to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09747

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 4. Reference area comprised of pine, gambel oak, smooth brome and indian rice grass.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09747