

# Final Reclamation Inspection

September 1st, 2023

Operator: BP American Production Co - 10000

Location ID: 325941

Inspection Document #: 714000010

La Plata County, CO

Township: NESE 18 35N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 1.** Overview photo of the disturbance. Area remains unreclaimed.

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 2.** Musk thistle observed flowering on location that need to be controlled over 20 individuals estimated.

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 3.** Fill slope on southern edge of disturbance.

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 4.** equipment stored just off of location.

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 5.** Overview of access road at entrance of disturbance that remains unreclaimed.

Inspection Photos  
Location Name: Litton Federal 1  
Location ID: 325941



**Photo 6.** Reference area comprised of pine, gambel oak, western wheatgrass and sandberg bluegrass.

