

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/5-10

Location ID: 322536

Date: 9/21/2023



Entrance to Pad/Wellheads – Photo #06483



SE Corner of Pad/Wellheads – Photo #06484

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, MV/5-10

Location ID: 322536

Date: 9/21/2023



Separators – Photo #06487



Tank Battery – Photo #06488

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/5-10

Location ID: 322536

Date: 9/21/2023



Sep 21, 2023 at 09:34:52

Unprotected Soil Stockpile – Photo #06485



Sep 21, 2023 at 09:35:17
Garden Gulch
Parachute CO 81638
United States

Unprotected Soil Stockpile – Photo #06486