

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA LLC-67S96W/3SENE

Location ID: 324067

Date: 9/21/2023



Entrance to Location – Photo #06528



NE Corner of Location – Photo #06529

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA LLC-67S96W/3SENE

Location ID: 324067

Date: 9/21/2023



Wellhead – Photo #06530



Separator – Photo #06531

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA LLC-67S96W/3SENE

Location ID: 324067

Date: 9/21/2023



Tank Battery – Photo #06532



Rill Erosion Cutting Through Lease Road – Photo #06533