

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3SWNE

Location ID: 334802

Date: 9/21/2023



Entrance to Location – Photo #06541



Wellheads – Photo #06542

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3SWNE

Location ID: 334802

Date: 9/21/2023



Separators – Photo #06545



Tank Battery – Photo #06547

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3SWNE

Location ID: 334802

Date: 9/21/2023



**Rill Erosion Cutting Through Lease Road – Photo #06544**