

Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880



Debris from 5/31 inspection



Wellhead sign

Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880



Open end tank valve



Insufficient tank label

Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880



**Debris from 5/31 inspection**



**Tank berm burrow**

Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880



**Insufficient tank berm**



**Debris. Open end tank valve**

Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880



**Weeds**



**Weeds. Insufficient tank berm**

**Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880**



**Location view from Northwest corner**



**Location view from Northeast corner**

**Argali Exploration Company  
Federal-Blue Gravel 1-23  
Location ID: 312880**



**Location view from Southeast corner**



**Location view from Southwest corner**