

WELL NAME: SHEEP MOUNTAIN UNIT WELL 4-23-L, API #: 055-06314 INSP. # 695108643



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: There is no labeling at the chemical tank next to the well. Install sign to comply with Rule 605.h. THIS IS THE SECOND NOTICE OF THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.





PHOTO 5: There is a dripping leak coming from the chemical tank line next to the well and there is no lid on the tank. Implement or modify BMPs for improved material handling and spill prevention. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.

