

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 1: Wellhead



Photo 2: TA Wellhead, Weeds



Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Energy & Carbon Management Commission
40.1647, -104.7027, 1482.8m, 358°
Sep 22, 2023 11:07:14



Energy & Carbon Management Commission
40.1647, -104.70263, 1482.7m, 13°
Sep 22, 2023 11:07:24

Photo 3: TA Wellhead, Weeds

Photo 4: TA Wellheads, Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537




Photo 5: TA Wellhead, Weeds



Photo 6: TA Wellhead, Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 7: TA Wellhead, Weeds



Photo 8: Weeds



Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 9: Weeds



Photo 10: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 11: Weeds



Photo 12: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 13: Weeds



Photo 14: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 15: Weeds



Photo 16: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 17: Weeds



Photo 18: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 19: Weeds



Photo 20: Weeds

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537




Photo 21: Weeds