

Inspection Photos
Location Name: Nichols 37N-31HZ
Location ID: 429182



Photo 1: Wellhead




Photo 2: Unused/disconnected equipment



Inspection Photos
Location Name: Nichols 37N-31HZ
Location ID: 429182




Photo 3: Wellhead



Photo 4: Wellhead



Inspection Photos
Location Name: Nichols 37N-31HZ
Location ID: 429182



Photo 5: Pumpjack




Photo 6: Wellhead



Inspection Photos
Location Name: Nichols 37N-31HZ
Location ID: 429182



Photo 7: Unused equipment



Photo 8: Wellhead

Inspection Photos
Location Name: Nichols 37N-31HZ
Location ID: 429182



Energy & Carbon Management Commission
 40.16081, -104.70488, 1486.1m, 339°
 Sep 21, 2023 12:40:01

Photo 9: Tank Battery



Energy & Carbon Management Commission
 40.16094, -104.70428, 1487.3m, 322°
 Sep 21, 2023 12:44:19

Photo 10: Gas meter not annually calibrated

