

## Inspection Photos

Location Name: HSR CHURCH-62N62W 17SESW Tank Battery

Location ID: 329979



Sign



## Inspection Photos

Location Name: HSR CHURCH-62N62W 17SESW Tank Battery

Location ID: 329979



**Tank Battery & Overgrown Vegetation**



**Production Equipment & Overgrown Vegetation**



## Inspection Photos

Location Name: HSR CHURCH-62N62W 17SESW Tank Battery

Location ID: 329979



**Gas Meter Run & Overgrown Vegetation**



**Weathered Berms & Overgrown Vegetation**





## Inspection Photos

Location Name: HSR CHURCH-62N62W 17SESW Tank Battery

Location ID: 329979



**Weathered Berms & Overgrown Vegetation**



**Weathered Berms & Overgrown Vegetation**

## Inspection Photos

Location Name: HSR CHURCH-62N62W 17SESW Tank Battery

Location ID: 329979



**Stained Soil**

