


Inspection Photos

Location Name: KLEIN-62N62W 8NENW Tank Battery

Location ID: 318664



Access road covered in overgrown vegetation



Access road covered in overgrown vegetation

Inspection Photos

Location Name: KLEIN-62N62W 8NENW Tank Battery

Location ID: 318664



Gas meter run & Overgrown Vegetation



Production Equipment & Overgrown Vegetation

Inspection Photos
Location Name: KLEIN-62N62W 8NENW Tank Battery
Location ID: 318664



Tank Battery & Overgrown Vegetation

Sign

Inspection Photos

Location Name: KLEIN-62N62W 8NENW Tank Battery

Location ID: 318664



Missing Capacity Label & Overgrown Vegetation

Missing Capacity Label & Overgrown Vegetation

Inspection Photos

Location Name: KLEIN-62N62W 8NENW Tank Battery

Location ID: 318664



Missing Capacity Label & Overgrown Vegetation



Missing Capacity Label & Overgrown Vegetation