

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/19/2023

Document Number:

699107378

FIELD INSPECTION FORMLoc ID 317912 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10528

Name of Operator: ARCH OIL & GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240164	WELL	SI	09/01/2020	OW	123-07952	KAUFMAN 4	SI

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Incorrect operator sign needs to be updated. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g		Date: 10/27/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 240164 Type: WELL API Number: 123-07952 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI, Well is overdue for Mechanical Integrity Test.Corrective Action: MIT requires 10-day notification via Form 42. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.Date: 10/27/2023**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 9/19/23 at approximately 0943hrs I, Inspector Adam Burns, Conducted an on-site inspection at of KP Arch Oil & Gas LLC. API #05-123-07952 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Incorrect operator sign needs to be updated. Install sign to comply with Rule 605.g. With a Corrective Action date of 10/27/23</p> <p>Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. With a Corrective Action date of 10/27/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	09/19/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403534851	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255820
699107379	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255787