

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 914 From entrance to location



Photo # 915 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 916 Location




Photo # 917 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Sep 25, 2023 at 2:03:27 PM
CO

Photo # 918 Location



Sep 25, 2023 at 2:05:16 PM
CO

Photo # 919 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 920 Stained gravel



Photo # 921 Stained gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 922 Stained gravel