

Inspection Photos

Location Name: at Gorges 2-62-33 NWNW Tank Battery

Facility ID: 450527



September 25, 2023 at 10:36 AM

+40.1009, -104.3361

260° W

Weld County

Energy & Carbon Management Commission

Incorrect Operator sign & Overgrown Vegetation



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: at Gorges 2-62-33 NWNW Tank Battery

Facility ID: 450527



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: at Gorges 2-62-33 NWNW Tank Battery

Facility ID: 450527



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: Gorges 2-62-33 NWNW Tank Battery

Facility ID: 450527



Stained soil



Debris