

Inspection Photos

Loc: 334211

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/25/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location. There are 2 producing well at the location.



Inspection Photos



Photo 2. South side of the location facing west.



Inspection Photos



Photo 3. Facing northwest toward the produced water pit. The water level is nearing 2 ft. freeboard..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:334211 | Date: 9/25/2023