

Inspection Photos  
Location Name: Walchle 2-27-5-43  
API Number: 125-10013



1. Well Sign.



2. View of wellhead. Note weeds.



**Inspection Photos**  
**Location Name: Walchle 2-27-5-43**  
**API Number: 125-10013**



**3. View of concrete pad. Note weeds and debris.**



**4. Meter shed. Note Pump Jack barriers left at location. Note weeds.**

Inspection Photos  
Location Name: Walchle 2-27-5-43  
API Number: 125-10013



5. Chart in Meter Box at time of inspection.

Omimex Meter Test Report

Well Name Walchle 2-27-5-43 Date 8-27-20

Diff. Range 0 to 100  
Static Range 0 to 150  
Temp Average 60

Plate 1250

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Inspector [Signature]

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150)	75	75 (150)
0	0	0

2023.08.22 14:16

6. Calibration/Test Log in meter shed at time of inspection.



**Inspection Photos**  
**Location Name: Walchle 2-27-5-43**  
**API Number: 125-10013**



**7. One of three down deadmen markers.**



**8. Location over view.**