

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad

Location ID: 324140



Photo # 760 From entrance to location

Photo # 761 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad

Location ID: 324140



Photo # 762 Location




Photo # 763 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad

Location ID: 324140




Photo # 764 Location



Photo # 765 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad

Location ID: 324140



Photo # 766 Location/chemical tank label illegible



Photo # 767 Wildlife protection needs maintenance