

# Inspection Photos

Loc: 309410

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the main access road. The road has been recently graded. This culvert is partially filled in with sediment.





## Inspection Photos



**Photo 2.** Facing west along the road. This culvert has filled in with sediment.  
Lat/Long:37.14485,-104.03594.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309410 | Date: 9/28/2023



## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309410 | Date: 9/28/2023