

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:29:41 AM
39.544999,-104.542189
Elbert County
CEMC



Pic 1 wellheads

Sep 8, 2023 at 11:30:56 AM
39.546019,-104.542533
Elbert County
CEMC



Pic 2 gas generators for ESP

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:31:30 AM
39.545183,-104.542906
Elbert County
CEMC



Pic 3 compressor

Sep 8, 2023 at 11:31:39 AM
39.545202,-104.543035
Elbert County
CEMC



Pic 4 compressor

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:31:51 AM
39.545202,-104.543035
Elbert County
CEMC



Pic 5 Separators / GMR

Sep 8, 2023 at 11:33:41 AM
39.545240,-104.543156
CEMC



Pic 6 Generator, electric equipment

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:28:56 AM
39.545310,-104.543455
Elbert County
CEMC



Pic 7 ECD, black smoke was observed burning from ECD at time of inspection.

Sep 8, 2023 at 11:34:20 AM
39.545471,-104.543881
Elbert County
CEMC



Pic 8 VRU, VRT, small leak detected by CDPHE FLIR inspection.

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811



Pic 9 minor leak detected by CDPHE FLIR inspector.



Pic 10 Tanks

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:36:23 AM
39.546690,-104.543011
Elbert County
CEMC



Pic 11 Air monitoring equipment on north end of location

Sep 8, 2023 at 11:39:43 AM
39.544751,-104.542793
Elbert County
CEMC



Pic 12 air monitoring equipment on south end of location

Inspection Photos
Location Name: Vulcan 6-64 10-8 1HN
Location ID: 478811

Sep 8, 2023 at 11:40:44 AM
39.545615,-104.544321
Elbert County
CEMC



Pic 13 Air monitoring equipment on west end of location.