

Inspection Photos
Location Name: Clifford Causey 20
Location ID: 319633



Pic 1 wellhead / pump jack



Pic 2 unused tubing on location needs to be removed

Inspection Photos
Location Name: Clifford Causey 20
Location ID: 319633



Pic 3 trash and unused equipment on location needs to be removed



Pic 4 unused trash on location needs to be removed