

Operator: Extraction Oil and Gas
Location Name: DF Ranch PC NI Battery Location
Loc ID: 448675
Inspection: 696305290



Exhibit A

CA: North crude tank- capacity label has faded and is no longer visible. Install signs to comply with Rule 605.h.

CA Resolution: Operator has installed a capacity label on the North crude tank to comply with ECMC Rule 605.h.