

Inspection Photos

Location Name: HSR Anne State-63N61W 7NESE Tank Battery

Location ID: 329904



Tank Battery & Overgrown Vegetation

Overgrown Vegetation



Inspection Photos

Location Name: HSR Anne State-63N61W 7NESE Tank Battery

Location ID: 329904



Overgrown Vegetation



Overgrown Vegetation


Inspection Photos

Location Name: HSR Anne State-63N61W 7NESE Tank Battery

Location ID: 329904



Unused Equipment



Overgrown Vegetation