

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100177

FIELD INSPECTION FORM

 Loc ID 319419 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10547
 Name of Operator: HELENA RESOURCES INC
 Address: 2960 SIMMS DR
 City: LAKEWOOD State: CO Zip: 80215
Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pagano, Theodore	(970) 590-3944	tapagano@helena-resources.com	
Raney, Jeremy	303-775-3647	Jer.raney@gmail.com	

General Comment:

This is an environmental inspection for Location ID 319419 Thurman Hays 1. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Trash/debris/weeds throuhgout pad location. Statewide unnecessary equipment, weeds, waste, and trash requirements

Corrective Action: Comply with Rule 606

Date: 10/19/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Although trash/debris on site may not be operator related, operator is responsible for upkeep on their pad.	robinsotl	10/05/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100178	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275715