

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100179

FIELD INSPECTION FORMLoc ID 432916 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspection@pdce.com	All Inspections
,		cogccinspection@pdce.com	
,		cogccinspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Locatin ID 432916 Sorin Natural Resources pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: trash/metal debris near wells.

Corrective Action: Comply with Rule 606

Date: 10/19/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: No spills present.

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100180	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275716