

Caerus  
A36A  
Location ID: 335641



Well heads



Location



Caerus  
A36A  
Location ID: 335641




Tank battery lacking signage



Tank battery lacking signage



Caerus  
A36A  
Location ID: 335641



Separators



Spill kit



Caerus  
A36A  
Location ID: 335641



Well head signage



Containment is full of fluid



Caerus  
A36A  
Location ID: 335641



Missing cap/plug



Location



Caerus  
A36A  
Location ID: 335641



Debris



Debris



Caerus  
A36A  
Location ID: 335641



Debris



Debris



Caerus  
A36A  
Location ID: 335641



Gas cans not contained



Gas cans not contained