

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1566 From entrance to location



Photo # 1567 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1568 Location



Photo # 1569 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1570 Location



Photo # 1571 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1572 Location



Photo # 1573 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1574 Location




Photo # 1575 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1576 Open ended pipe/wildlife hazard



Photo # 1577 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1578 Hole in liner/liner needs maintenance



Photo # 1579 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1580 Hole in liner/liner needs maintenance



Photo # 1581 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1582 Holes in liner/liner needs maintenance



Photo # 1583 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 1584 Debris



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources