

Inspection Photos

Location Name: CAERUS PICEANCE LLC B31 Pad

Location #: 335307



Photo # 1722 From entrance to location




Photo # 1723 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 1724 Location



Photo # 1725 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 1726 Location



Photo # 1727 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 1728 Location



Photo # 1729 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC B31 Pad

Location #: 335307



Photo # 1730 Burner tube on production tank open ended/wildlife hazard



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources