

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N32 Pad

Location #: 334856



Photo # 1794 From entrance to location



Photo # 1795 Location

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 1796 Location**



**Photo # 1797 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 1798 Location**



**Photo # 1799 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 1800 Flowline heating insulation open ended**



**Photo # 1801 Flowline heating insulation open ended**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N32 Pad

Location #: 334856



Photo # 1802 Open ended load line