

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
403555105

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
10/10/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10243  
Name of Operator: GMT EXPLORATION COMPANY LLC  
Address: 4949 S NIAGARA ST SUITE 250  
City: DENVER State: CO Zip: 80237

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Blair, Max</u>	<u>720-862-4503</u>	<u>mblair@gmtexploration.com</u>
<u>Silver, Randy</u>		<u>randy.silver@state.co.us</u>
		<u>kate.fury@state.co.us</u>
		<u>jennifer.morse@state.co.us</u>
<u>Eberhardt, Whitney</u>	<u>303-586-9289</u>	<u>w.eberhardt@gmtexploration.com</u>
		<u>sara.m.hansen@state.co.us</u>
		<u>jennifer.mattox@state.co.us</u>
		<u>joseph.wright@state.co.us</u>
<u>Cox, BJ</u>	<u>303-586-9274</u>	<u>bjcox@gmtexploration.com</u>
		<u>dida.osborne@state.co.us</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699504999  
Inspection Date: 09/08/2023 FIR Submit Date: 09/08/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GMT EXPLORATION COMPANY LLC Company Number: 10243  
Address: 4949 S NIAGARA ST SUITE 250  
City: DENVER State: CO Zip: 80237

LOCATION - Location ID: 478811

Location Name: Vulcan Number: 6-64 10-8 County: ELBERT  
Pad  
Qtrqr: SENW Sec: 10 Twp: 6S Range: 64W Meridian: 6  
Latitude: 39.545813 Longitude: -104.542233

FACILITY - API Number: 05-039-00 Facility ID: 478804  
Facility Name: Vulcan 6-64 10-8 Number: 1HN

Qtrqtr: SENW Sec: 10 Twp: 6S Range: 64W Meridian: 6  
Latitude: 39.545813 Longitude: -104.542233

CORRECTIVE ACTIONS:

**1** CA# 182933

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 09/23/2023

Response: CA COMPLETED

Date of Completion: 09/08/2023

Operator Comment: At the time of the inspection the compressor was being blown down to perform a scheduled PM so the pumper explained the situation. GMT's pumper also fixed the lead on the VRY while the inspector was on site.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Whitney Eberhardt

Signed: \_\_\_\_\_

Title: Engineer Technician

Date: 10/10/2023 8:53:49 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files