

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 10/5/2023



Entrance to Location – Photo #06821



Entrance to Location – Photo #06822

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 10/5/2023



Oct 5, 2023 at 10:14:28  
3555 CR-215  
Parachute CO 81635  
United States

Wellheads – Photo #06825



Oct 5, 2023 at 10:13:29  
3555 CR-215  
Parachute CO 81635  
United States

Separators – Photo #06824



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 10/5/2023



**Tank Battery – Photo #06823**



**Location Lacks Stabilization – Photo #06827**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 10/5/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #06828