

Inspection Photos
Location Name: Smuggler 16-10-62
Location ID: 418211



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Smuggler 16-10-62
Location ID: 418211



Photo 3 – Propane Tank



Photo 4 – Heater Treater, ECD and Flare

Inspection Photos
Location Name: Smuggler 16-10-62
Location ID: 418211



Photo 5 – Backside of Tanks



Photo 6 – Tank Battery

Inspection Photos
Location Name: Smuggler 16-10-62
Location ID: 418211




Photo 7 – Tank Battery Sign



Photo 8 – Water Tank Labels