

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Location & No Battery Sign

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



No Capacity or NFPA Placard



Unmarked Risers

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Unmarked Riser



Overgrown Vegetation