

Inspection Photos
Location Name: Conoco Fee 66#492
Location ID: 322273



Photo 1 well head



Photo 2 Crude oil tank

Inspection Photos
Location Name: Conoco Fee 66#492
Location ID: 322273



Photo 3 trash, stained soil around crude oil tank



Photo 4 Sign, unmarked container stairs held on by cable in disrepair, rocks, wood.

Inspection Photos
Location Name: Conoco Fee 66#492
Location ID: 322273



Photo 5 tank stairs in disrepair.