

Inspection Photos
Location Name: marjo #M2
Location ID: 322261



Photo 1 Well head



Photo 2 crude oil tank



Inspection Photos
Location Name: marjo #M2
Location ID: 322261



Photo 3 Crude oil tank



Photo 4 gauge hatch open

Inspection Photos
Location Name: marjo #M2
Location ID: 322261



Photo 5 crude oil tank