

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14SENE

Location ID: 334735

Date: 10/10/2023



Entrance to Location – Photo #06855



Wellheads/Lack of Stabilization – Photo #06857

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14SENE

Location ID: 334735

Date: 10/10/2023



Separators – Photo #06859



Tank Battery – Photo #06858

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14SENE

Location ID: 334735

Date: 10/10/2023



Lack of Stabilization – Photo #06856



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06860**