

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 1 – Flare Weeds



Photo 2 – Location Overview – Weeds

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 3 – ECD



Photo 4 – Gas Meter House

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 5 – Heater Treater – Weeds



Photo 6 – Tank Battery – Weeds

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 7 – Tank Battery Sign

Photo 8 – Weeds on South Side of Location

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 9 – Weeds looking North



Photo 10 – Pumping Unit



Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 11 – Wellhead – Weeds




Photo 12 – Wellhead – Stained Soil



Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



Photo 13 – Stained Soil and Oily Waste at Pumping Unit



Photo 14 – Unmarked Riser

Inspection Photos
Location Name: Cass Farms 11-9H
Location ID: 420717



ECMC
40.59508, -104.33475, 4780.5ft
10/05/2023 13:05:06

Photo 15 – Weeds looking South