

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100179

FIELD INSPECTION FORM

Loc ID 432916 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
,		cogccinspection@pdce.com	All Inspections
,		COGCCInspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Locatin ID 432916 Sorin Natural Resources pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: trash/metal debris near wells.

Corrective Action: Comply with Rule 606

Date: 10/19/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment: No spills present.

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403552141	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275729
694100180	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275716