

Inspection Photos
Location Name: HSR-Camp 4-31X
Location ID: 329196



Photo 1: signage

Photo 2: Location of PA wellhead



Inspection Photos
Location Name: HSR-Camp 4-31X
Location ID: 329196



Photo 3: Equipment removed



Photo 4: Unused equipment