

# Interim Reclamation and Stormwater Inspection

Date: 10/05/2023

Operator: H&M PETROLEUM CORPORATION - 10032

Location ID: 458288

Inspection Document #: 708200603

Logan County, CO

NWNE Section 36 T12N R55W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



**Photo 1.** Debris on location south of tank battery.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



**Photo 2.** Stained soil and leaking equipment/fitting at tank battery.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



10/5/23, 11:43 AM  
176° S  
ECMC

**Photo 3.** Drum not within adequate secondary containment.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



**Photo 4.** Stained soil observed near drum without adequate secondary containment.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



**Photo 5.** Degraded straw wattles are now considered debris and need to be removed.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



**Photo 6.** Stained soil observed near wellhead.



Inspection Photos  
Location Name: State BDB 1  
Location ID: 458288



10/5/23, 11:45 AM  
279° W  
ECMC



10/5/23, 11:45 AM  
51° NE  
ECMC

**Photos 7 & 8.** Erosion degradation occurring around pump jack unit due to unstabilized soils.