

## Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RWF 14-4 Pad

Location # 324111



Photo # 2502 From entrance to location




Photo # 2503 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RWF 14-4 Pad

Location # 324111



Photo # 2504 Location



Photo # 2505 Location





## Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RWF 14-4 Pad

Location # 324111



Photo # 2506 Location



Photo # 2507 Netting/Wildlife protection needs maintenance

## Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RWF 14-4 Pad

Location # 324111



Oct 11, 2023 at 12:56:50 PM  
CO

Photo # 2508 Open ended load line



Oct 11, 2023 at 12:59:41 PM  
CO

Photo # 2509 Debris