

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 85-34 Pad

Location # 324015



Photo # 2369 From entrance to location



Photo # 2370 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 85-34 Pad

Location # 324015



Photo # 2371 Location



Photo # 2372 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 85-34 Pad

Location # 324015



Photo # 2373 Location



Photo # 2374 Open ended pipe/wildlife hazard



Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY RMV 85-34 Pad

Location # 324015



Photo # 2375 Open ended pipe/wildlife hazard