

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

Location ID: 311561

Date: 10/12/2023



Location Entrance – Photo #06882



Wellheads – Photo #06883

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

Location ID: 311561

Date: 10/12/2023



Separators – Photo #06884



Tank Battery – Photo #06885

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

Location ID: 311561

Date: 10/12/2023



Sediment Run-On to Location – Photo #06888



Sediment Run-On to Location – Photo #06889