

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 10/12/2023



Oct 12, 2023 at 13:57:16
8311 CR-215
Parachute CO 81650
United States



Oct 12, 2023 at 13:59:15
3555 CR-215
Parachute CO 81635
United States

Location Entrance – Photo #06900

Wellhead – Photo #06902

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 10/12/2023



Separator – Photo #06905



Tank Battery – Photo #06907

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 10/12/2023



Location Lacks Stabilization – Photo #06903



Insufficient Erosion Control – Photo #06908

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 10/12/2023



Insufficient Erosion Control – Photo #06901



Insufficient Erosion Control/Sediment Run-on to Location –
Photo #06906

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 10/12/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06909