

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Oct 12, 2023 at 12:02:35 PM
CO

Photo # 2603 From entrance to location



Oct 12, 2023 at 12:02:43 PM
CO

Photo # 2604 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 2605 Location



Photo # 2606 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 2607 Location



Photo # 2608 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 2609 Location



Photo # 2610 RWF 343-33 wellhead sign some info is illegible



Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 2611 Debris



Photo # 2612 Debris



Inspection Photos

Location Name: TEP Rocky Mountain LLC BERNKLAU RMV 110-33 Pad

Location # 334874



Photo # 2613 Unmarked deadman



Photo # 2614 Unmarked deadman