

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612




**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 2 7S92W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2305 Erosion/lack of stabilization on slope



Photo # 2306 Erosion/lack of stabilization on slope

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2307 Erosion/lack of stabilization on slope



Photo # 2308 Erosion/lack of stabilization on slope

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2309 Erosion/lack of stabilization on slope



Photo # 2310 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2311 Erosion & transport of sediment off location



Photo # 2312 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2313 Erosion & transport of sediment off location

Photo # 2314 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad
Location # 311612



Photo # 2315 Erosion & transport of sediment off location