

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2279 From entrance to location



Photo # 2280 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612




Photo # 2281 Location



Photo # 2282 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2283 Location



Photo # 2284 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2285 Location



Photo # 2286 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2287 Location



Photo # 2288 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612




Photo # 2289 Location



Photo # 2290 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2291 Methanol tank lacks required information



Photo # 2292 Methanol tank lacks required information



Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2293 Methanol tank lacks required information



Photo # 2294 Methanol tank lacks required information

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2295 Unused equipment/ECD is disconnected



Photo # 2296 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2297 Unused equipment/ECD is disconnected



Photo # 2298 Unmarked deadman

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2299 Debris



Photo # 2300 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2301 Unused equipment



Photo # 2302 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2303 Debris



Photo # 2304 Debris