

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2023

Submitted Date:

10/09/2023

Document Number:

710500054

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist
Costa, Ryan		ryan.costa@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485210	SPILL OR RELEASE	AC	10/04/2023		-	SPILL/RELEASE POINT	EI

General Comment:

This is an Environmental Inspection for the Wapiti, Produced Water Gathering Line Spill, Facility ID 485210, located in Las Animas County, Co

Inspected Facilities

Facility ID: 485210 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: On 9/29/2023 Wapiti Operating had a release at approximately 1300 hrs. It was estimated 13,000 barrels of produced water was released. The line was isolated and immediately repaired. During the site inspection, ECMC determined the waters from the release impacted an ephemeral drainage identified as waters of the state approximately 100 feet east of the spill.

Corrective Action: Per Rule 912.b.(9) Operators will report a Spill or Release of any size that impacts or threatens to impact surface waters to the Director and to the Environmental Release/Incident Report Hotline (1-877-518-5608). Spills and Releases that impact or threaten a Public Water System intake, as described in Rules 411.a.(4) & 411.b.(5), will be verbally reported to the emergency contact for that facility concurrent with providing the 24 Hour Notification to the Director pursuant to Rule 912.b.(1). Operator shall submit correspondents on the 10 day supplemental Form 19 due on 10/9/2023.

Date: 10/09/2023

Reportable: YES

GPS: Lat 37.030554

Long -104.803534

Proximity to Surface Water: 100

Depth to Ground Water: 10

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat _____ Long _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Operator shall comply with Rule 912.c. Remediation of Spills or Releases.
If the spill remediation exceeds 90 days from initial release date the Operator will proceed with remediation efforts under a form 27 Per Rule 912.b.(6)

Corrective Action: Comply with Rule 912.c. and Rule 912.b.(6).

Date: 12/28/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Per Rule 912.b.(9) Operators will report a Spill or Release of any size that impacts or threatens to impact surface waters to the Director and to the Environmental Release/Incident Report Hotline (1-877-518-5608). Spills and Releases that impact or threaten a Public Water System intake, as described in Rules 411.a.(4) & 411.b.(5), will be verbally reported to the emergency contact for that facility concurrent with providing the 24 Hour Notification to the Director pursuant to Rule 912.b.(1). Operator shall submit correspondents on the 10-day supplemental form 19 due on 10/9/2023.	sanchezcc	10/09/2023
Operator shall comply with Rule 912.c. Remediation of Spills or Releases. If the spill remediation exceeds 90 days from initial release date the Operator will proceed with remediation efforts under a form 27 Per Rule 912.b.(6) Comply with Rule 912.c. and Rule 912.b.(6).	sanchezcc	10/09/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403554810	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278476
710500055	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278471